

Titan Expert and Titan Tiger Touch release notes 4.1.9

This release is an upgrade for Release 4.1, it addresses two problems found by a small number of users. Release 4.1 should be installed before installing this upgrade.

- 1 In some circumstances the console loses communication with the software copy protection.
- 2 When using Luminex Ethernet boxes multiple nodes would be displayed even though only one box was connected.

Background Information.

These are two separate software lock (dongle issues) issues.

- 1 Lost communication to the software lock once the console is running, which is identified with an on screen message. This problem is rectified by installing software release 4.1.9 which reads the Software Lock in a different way.
- 2 Lost communication during startup which is identified by the BIOS screen stopping during the initial memory check. This problem is fully resolved by carrying out ECN-0191 which moves the Software Lock (Dongle) to a totally different USB port.

Release 4.1.9 can be downloaded from here:

for the Pearl Expert

<http://www.avolitesdownload.com/Support/Consoles/PearlExpert.aspx>

or for Tiger Touch

<http://www.avolitesdownload.com/Support/Consoles/TigerTouch.aspx>

ECN-0191 (Dongle Connection Point Change) can be downloaded for:

<http://www.avolites.com/support/ecns/ecn-index.htm>