

Avolites Ltd.
Engineering Change Notice

Title	Pearl Expert Touch Wing LED flicker
ECN Number	ECN-0188
Equipment	Pearl Expert Touch Wing
Author	Adam Proffitt
Drawing Number	
Date	13/10/10

Reason for ECN	Various LEDs flicker on the Pearl Expert Touch Wing. This problem can appear as randomly flickering LEDs, but otherwise operation of the wing is not affected.
Special Parts required	Firmware ew_sb.hex file
Special Tools required	Pearl Expert console

Work Required	<p>The firmware needs to be updated.</p> <p>The Avolites FAQ 10030 describes how to update panel firmware using the UsbExpert Console utility. Contact the service dept. at Avolites to receive a .zip file with the FAQ and firmware file.</p>
----------------------	---