

Avolites Ltd.


Engineering Change Notice

Title	Trimming the links on a Sapphire 2000 SMF pcb.
ECN Number	ECN-0137
Equipment	Sapphire 2000 consoles with the following serial numbers :- 2117 to 2130
Author	Alwyn Fernandes
Drawing Number	None
Date	20/04/2001


Reason for ECN	Console locks when pressure is applied to the Master/Memory Fader Panel because links short to drawer cover, especially since this has been raised to improve clearance for the graphic tablet.
Special Parts required	none
Special Tools required	a pair of wire cutters

Work Required


The picture below shows where the three links on the SMF boards are located. All the exposed pins on these links should then be trimmed in half using a standard pair of cutters - see pictures below.



Avolites Ltd.
Engineering Change Notice



Before trimming



After trimming

Avolites Ltd.
Engineering Change Notice



Before trimming



After trimming

End of ECN