Avolites Ltd. Engineering Change Notice

Title ECN Number: Equipment: Date: Author: Revision:	Sapphire 2000 Lamps ECN-0107 Sapphire 2000 25/03/99 Ric 1.0
Reason for ECN:	Borris 2, 5volt lamp output is not fused
Special Parts Required:	In Line fuse holder and 1A fuse.
Special Tools Required:	none

Work Required:

- 1 2 Cut 5 volt wire between Power connector and lamp switch Fit in line fuse holder and fuse