Avolites Ltd. Engineering Change Notice

ALG video card modification
ECN-0123
All desks
Adam Proffitt
19/06/00

Reason for ECN	It was found that interference (eg from a mains cable) could affect unused address lines LA23 – LA17 on the video card.
Special Parts required	None
Special Tools required	None

Work Required

Pins C2 – C8 should be connected to anode of diode D1 on AP9707 (has ALG2032+ Chipset) circuit board.(The anode is the end nearest to the marking D1 on the board.) See photograph.

