

Avolites Ltd.
Engineering Change Notice

Title	Borris 2 reset line
ECN Number	ECN-0124
Equipment	Borris 2 desks : Sapphire 2000, Pearl 2000, Azure
Author	Adam Proffitt
Drawing Number	
Date	30/06/00

Reason for ECN	Noise can enter on reset line, causing processor or other Ic's to reset.
Special Parts required	470pF capacitor – avo part no. 06-03-0016
Special Tools required	

Work Required
Fit 470pF capacitor between GND and RST on MAS101. (MAS101 is near external reset connection) External reset connection uses MAS100.