## **Avolites Ltd. Engineering Change Notice**

Title	Floppy Adaptor Board
ECN Number	ECN-0127
Equipment	All desks using a Borris2 motherboard.
Author	Alwyn Fernandes
Drawing Number	
Date	25/07/00

Reason for ECN	The DIL floppy controller chip is no longer available
Special Parts required	Replacement board FAB 2150A (1201-2150AA)
Special Tools required	None

## Work Required

- Carefully fit the assembled floppy adaptor board (FAB 2150A) into the 40Way DIL socket (IC505) on the Borris2 motherboard.
- Update the KATYA Gal (IC111) to KATYA 60.