


Avolites LTD Engineering Change Notice.

ECN title	Quartz – Ferrite protection		
ECN Number	ECN-210		
Related Product(s)	All Quartz consoles before SN 1701		
Date / Author	23/11/2017	Greg K	
Reasons for ECN	Occasionally the mains wires ferrite stuck in the fan		
Parts required	Cable-tie		
Tools required	Side cutters and No.2 Pozi or T20 Torx drive		
Estimated time	5 Minutes		




Disconnect the console from the Mains and other electrical connections




1. Open the console by removing the two screws at the front edge of the console, these screws may be No.2 Pozi or T20 Torx drive



2. Lift the front and hook the stand on the right side of the console to the moulding fixing.



3. Cable-tie two mains wires (the ones going around the ferrite) to the fan screw as shown on picture below



4. Flip the stand down and close the console with retained fixings

This concludes the ECN